




The Problem is: **LOSS of SERVICE**



The Solution is: **DPBO**

Exchange Side ← Remote Side



Downstream Power Back Off
at the Remote Terminal

The rate of power reduction and the
shape of PSD mask depend on ESEL



ELQ 2+ xDSL LINE QUALIFIER

- Provides templates for the qualification of local cables between remote terminal and customer premises when **DPBO** is applied
- ESEL** () measuring facility up to 120 dB